





Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
 Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
 Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
 Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
 / Rendelhető alkatrészek / Запасні частини / Reservní delovi / Резервни делови /
 Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļi

XX = AA, AD...

- 1 = A 860 886 XX
- 2 = A 860 887 NU
- 3 = A 860 888 NU
- 4 = A 962 136 NU
- 8 = A 960 944 NU
- 13 = A 860 889 NU




	P	bar	MIN. 0,5	MAX. 10		Q (3 bar)
	T	°C	MAX. 80	65 55		l/min 16



Ideal Standard International NV
 Corporate Village - Gent Building
 Da Vincilaan 2
 1935 Zaventem
 Belgium


www.idealstandardinternational.com



CERAPLUS

A 5776 .. A 5777 ..

0716 / A 866 498
 (+ A 865 612)
 Made in Germany



A 5776 ..

