









Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb
/ Rendelhető alkatrészek / Запасні частини / Reservni delovi / Резервни делови /
Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļi





Werkstoffliste / List of materials		
Pos.	Name	Material
1	Gehäuse housing	b020
2	Neoperleinsatz Neoperl insert	
3	Sicherungsring circlip	1.4122



DIN EN 1717
HD




max.
10 Nm



Ideal Standard International NV
Corporate Village - Gent Building
Da Vincilaan 2
1935 Zaventem
Belgium

www.idealstandardinternational.com



Pos.	Part No.
1	A 963 131 NU
2	A 963 132 NU
3	A 963 146 NU
4	A 962 594 NU
5	A 861 262 NU
6	A 960 706 NU
7	A 960 891 NU
8	A 962 480 NU
9	A 963 564 NU
10	A 963 427 NU
11	A 962 391 AA
12	A 962 481 NU
13	A 960 899 NU
14	A 962 384 AA



15	A 960 895 NU
16	A 962 484 AA
17	A 961 659 NU
18	A 962 388 AA
19	A 962 870 AA
20	A 960 704 NU
	A 962 476 NU
21	A 960 705 AA
22	A 861 252 NU












Ideal Standard

CERATHERM 100
A 5619 ..

0421 / A 866 317
Made in Germany





P	bar	MAX. 10	5	Q (3 bar)
T	°C	MAX. 80	65 55	l/min
				21