








Spare Parts / Ersatzteile / Pièces de recharge / Pezzi di Ricambio / Piezas de requesto /
Parte de reposição / Reserveonderdelen / Reservdelar / Reservedeler / Varaosat /
Vraosat / Varahlutir / Ανταλλακτικά / Yedek Parçalar / Náhradní díly / Náhradné diely /
Nadomestni deli / Резервни части / Запчасти / Części Zapasowe / Piese de schimb /
Rendelhető alkatrészek / Запасні частини / Reservní delovi / Резервни делови /
Резервни делови / Atsarginių dalių / Tellitavad varuosad / Rezervju daļu



A5776




F960965NU



Ideal Standard International NV
Corporate Village - Gent Building
Da Vincilaan 2
1935 Zaventem
Belgium

www.idealstandardinternational.com





- | | |
|----|--------------|
| 1 | B 961 003 AA |
| 2 | B 960 473 AA |
| 3 | A 963 309 NU |
| 4 | B 960 862 AA |
| 6 | A 861 181 NU |
| 7 | A 861 156 NU |
| 15 | B 960 859 AA |





CERAMIX BLUE
A 5825 ..








0719 / A 866 513
(+ A 865 612)

Made in Germany





The diagram illustrates the correct and incorrect way to use a faucet handle. On the left, an incorrect 'hook' grip is shown with a warning sign and a question mark. On the right, a correct 'thumb' grip is shown with thumbs-up icons.



 P 0,3 MPa 3 bar										
			0	1	2	3	4	5		
			°C	°C	°C	°C	°C	°C		
			50°C	15°C	50	49	44	40	35	33
			65°C	15°C	65	63	57	50	44	40
85°C	15°C	85	83	74	64	56	50			